



EXPRESS 55

Crewboat/ Utility Vessel

PRINCIPAL PARTICULARS

Year Built	1993
Place Built	Marrero, Louisiana, E.U.A
Design	Halter Marine Inc
Flag	Panama
Length Overall	37.89 m
Length BP	37.09 m
Breadth Moulded	8.56 m
Depth Moulded	3.44 m
Draft (max)	2.58 m
Freeboard (SLL)	11.60 m
Class	BV
Notation	I, Hull, Mach, Special Service Cargo, Utility Vessel, Unrestricted Navigation
GRT/ NRT	264.00 T / 79.00 T
Deadweight	253.66 T

DECK PARTICULARS

Clear Deck Area	120.00 m ²
Deck Carrying Load	120.00 T
Deck Strength	1.00 T/m ²

PERFORMANCE

Maximum Speed	16 Knots
Economic Speed	13 Knots

PROPULSION SYSTEM

Main Engines	4 x Detroit Diesel, 16V-92TAB, 960 BHP @ 2100 RPM, Total 4400 BHP
Auxiliary Engines	2 x DETROIT, 4-71 Inline, 60 kW @ 1200 RPM
Portable Generator	Nil
Emergency Generator	Nil
Bow Thruster	Driven PIME Front PTO, TRAC Hydraulic Thruster
Propellers	4 x Fixed Pitch Propellers, 4 Blade
Steering Gear System	2 x Duplex Electro Hydraulic pump system
Rudder	2 Units

TANK CAPACITIES

Fuel Oil	63.00 m ³
Fresh Water	64.00 m ³
Bilge	Nil
Ballast Water	31.00 m ³
Drill Water	Nil

CARGO DISCHARGE CAPACITIES

Fuel Oil Pump	1 x 23 m ³ /hr
Fresh Water Pump	Nil
Bilge	Nil



DECK EQUIPMENT

Anchor Windlass c/w Bow	Electric Motor 220 V/10 Amp
-------------------------	-----------------------------

ACCOMMODATION

Passenger Seats	139
Crew	1 x 1, 2 x 4 = 18

EXTERNAL FIRE-FIGHTING EQUIPMENT

Oil Dispersant System	SOPEP
-----------------------	-------

INTERNAL FIRE-FIGHTING & ANTI-POLLUTION EQUIPMENT

Emergency Fire Pump	YAMAR L40AE-DPY3-10122-3.1KW
CO2 Fi-Fi System	1 x Fixed CO2 System for Engine Room
Fire Detection & Alarm	Optical Smoke, Multi-Sensor Smoke & Heat Detector

LIFE-SAVING EQUIPMENT

Life Rafts	2 x 20 men, SOLAS Compliant
Rescue Boat c/w Davit	Nil

Particulars are believed to be correct but not guaranteed. Owners reserve the rights to amend the specifications without notifications. Particulars are entirely without warranty as to correctness and interested parties must inspect vessel's certificates, drawings or physical inspection of vessel.

